





1. Open the UPDD Settings program



2. Remove the current device



3. Add a new device



4. Follows the prompts and keep the default settings.

5. Calibrate the touch screen (go to the Start Menu => UPDD => Calibrate)



YOU'RE DONE!